



# UNIT III

# HEAT TREATMENT

**Engineering Materials and Metallurgy**

**KARTHICK B**

**ASSISTANT PROFESSOR / MECHANICAL ENGG**



# Heat Treatment






# Heat Treatment



Defined as the **controlled heating and cooling of metals** for the primary purpose of altering their properties (strength, ductility, hardness, toughness, machinability).





# Purpose of Heat Treatment



- To relieve internal stress
- To improve machinability
- To refine grain size
- To soften the metal
- To improve mechanical properties
- To increase resistance to wear, heat and corrosion.
- To change the chemical composition.



# Who uses Heat Treating ?



- Aircraft Industry
- Automobile Manufacturing
- Defense Sector
- Forging
- Foundry
- Heavy Machinery Manufacturing
- Powder Metal Industries





# Steps in Heat Treating Operation



## Loading

- Cleaning
- Pre-wash with coalescence
- De-phosphate system
- Spray rinse

- Heating
  - Preheating
  - Heating
  - Soak & diffusion
  - Pre-cooling


- Tempering
- Surface coating

- Quenching (Cooling)
- Post-wash

## • Unloading



# Heat Treating Processes





# Annealing



- It refers to a heat treatment in which the material is exposed to an elevated temperature for an extended time period and then **slowly cooled**.
- When an annealed part is allowed to cool in **the furnace**, it is called a **"full anneal"** heat treatment.







# Types of Annealing



- Full Annealing
- Process Annealing
- Stress Relief Annealing
- Recrystallization Annealing
- Spheroidise Annealing






# Full Annealing




## Main Objective:

- Soften the metal
- Relieve the stress
- Refine the structure.





# Full Annealing






# Full Annealing



- Temp is  $30 - 50^{\circ}\text{C}$  above the upper critical temp for hypo eutectoid steel.
- $30 - 50^{\circ}\text{C}$  above the lower critical temp for eutectoid steel.
- Cooling is done at the furnace at the rate of  $10-30^{\circ}\text{C}$  per hour.
- For hypo eutectoid steel the resulting microstructure is coarse pearlite and ferrite.






# Full Annealing



- For hypereutectoid steel annealing temp is  $30-50^{\circ}\text{C}$  above the **lower critical temp**.
- For hyper eutectoid steel the resulting microstructure is **coarse pearlite and cementite**.
- This process provides **high ductility and toughness**.






# Stress Relief Annealing



- Stress relief or **recovery annealing**.
- Annealing temp is at the range of **550-700°C**.
- **Uniform cooling** is mandatory.
- It eliminates the stress formed during welding, cold working, casting, quenching, machining.





# Need for SR Annealing




## ❖ Causes for stress:

- Plastic deformation during machining
- Non-uniform cooling
- Phase transformations between phases with different densities.

## ❖ Effect of Stress

- ✓ War page
- ✓ Crack
- ✓ Distortion






# Recrystallization Annealing



- It is a process in which distorted grains of cold worked material are **replaced by strain free new grains**.
- Recrystallization annealing is an annealing process at temperatures above the recrystallization temperature of the cold-worked material, **without phase transformation**
- The recrystallization temperature is not a constant for a material but depends on the amount of cold work, the annealing time, and other factors.
- $T_{(\text{recrystallization})} = 0.4 T_{(\text{melting})}$









# Recrystallization Annealing



It reduces the Dislocation density and converts elongated grains to equiaxed .







# Spheroidizing



- ❖ Converts
  - Lamellar Pearlite → Globular Pearlite
  - Plates of Cementite → Spheroids of Cementite





# Spheroidizing




## ❖ Main objectives of Spheroidising:

- To soften the steel
- Increase ductility and toughness
- Improves machinability and formability
- Reduces hardness, strength and wear resistance.

## ❖ Materials mainly concentrated

- Medium carbon steel
- High carbon (tool steel)

**Not used for Low carbon Steel**






# Spheroidizing



## Three ways of Spheroidising

- Prolong heating below Lower critical temperature and slow cooling.






# Spheroidizing



- Cycling between temperature and then relatively slow cooling.






# Spheroidizing



- For tool and high speed steel heating at the temperature range between  $750^{\circ}$  -  $800^{\circ}\text{C}$  then hold at this temperature and then slow cooling.





# THANK YOU

**Assessment** <https://play.kahoot.it/v2/?quizId=250c11af-904f-48bf-902f-148509a5835a>