



SNS COLLEGE OF TECHNOLOGY

(An Autonomous Institution)



COIMBATORE-35

**Accredited by NBA-AICTE and Accredited by NAAC – UGC with A+ Grade
Approved by AICTE, New Delhi & Affiliated to Anna University, Chennai**


DEPARTMENT OF ELECTRICAL AND ELECTRONICS ENGINEERING

**COURSE NAME: 19EET207/ SYNCHRONOUS AND INDUCTION
MACHINES**

II YEAR / IV SEMESTER


Unit 2 – SYNCHRONOUS MOTOR

Topic 5: Power input and power developed equations






GUESS THE TOPIC NAME...



2400 VAULT POWER MOTOR DESIGN
FACT overall unit dimensions.
ble design and magnetic flux
optimized, providing superior
characteristics well suited for
communication applications. 4 to
nection is available to match
per speed.





Synchronous Motor- phasor diagram

The phasor diagram of a synchronous motor is shown below. From the phasor diagram,

Let


V = Supply voltage / phase

I_a = Armature current / phase

R_a = Armature resistance / phase

α = Load angle

ϕ = Power factor angle





Synchronous Motor-Power developed



Input Power to Motor :

Motor input power / phase = $V I_a \cos \phi$

Total input power for 3- ϕ star-connected motor,

$$\begin{aligned} P &= \sqrt{3} V_L I_L \cos \phi \\ &= 3 V_{ph} I_{ph} \cos \phi \end{aligned}$$

Where

V_L and I_L are line values

V_{ph} and I_{ph} are phase values

Power Developed by Motor :

The mechanical power developed / phase,

P_m = Back emf * Armature current * Cosine of the angle between E_b and I_a

$$= E_b I_a \cos (\alpha - \phi) \text{ for lagging p.f}$$

$$= E_b I_a \cos (\alpha + \phi) \text{ for leading p.f}$$



Synchronous Motor-Power developed

The copper loss in a synchronous motor takes place in the armature windings.

Therefore,

$$\text{Armature copper loss / phase} = I_a^2 R_a$$

$$\text{Total copper loss} = 3 I_a^2 R_a$$

By subtracting the copper loss from the power input, we obtain the mechanical power developed by a synchronous motor as

$$P_m = P - P_{cu}$$

For three-phase,

$$P_m = \sqrt{3} I_L I_L \cos \phi - 3 I_a^2 R_a$$


Power Output of the Motor :

To obtain the power output we subtract the iron, friction, and excitation losses from the power developed.

Therefore,

Net output power, $P_{out} = P_m$ - iron, friction, and excitation losses.

The above two stages can be shown diagrammatically called as Power Flow Diagram of a Synchronous Motor



The power developed in a synchronous motor as follows.

Motor Input Power, P

1. Stator (Armature) copper loss P_{cu}
2. Mechanical power developed, P_m
 - a. Iron, friction, and excitation losses
 - b. Output power, P_{out}



Net Power Developed by a Synchronous Motor :

The expression for power developed by the synchronous motor in terms of α , θ , V , E_b , and Z_s are as follows :

Let

V = Supply voltage

E_b = Back emf / phase

α = Load angle

θ = Internal or Impedance angle = $\text{Tan}^{-1} (X_r / Z_s)$

I_a = Armature current / phase = E_r / Z_s

$Z_s = R_a + j X_s =$ Synchronous impedance

Mechanical power developed / phase

$$P_m = \frac{E_b V}{Z_s} \cos(\theta - \alpha) - \frac{E_b^2}{Z_s} \cos \theta$$



Net Power Developed by a Synchronous Motor :



The armature resistance is neglected

If R_a is neglected, then $Z_s \approx X_s$ and $\theta = 90^\circ$. substituting these values in the above equation

$$P_m = \frac{E_b V}{X_s} \cos(90 - \alpha) - \frac{E_b^2}{X_s} \cos 90^\circ$$

$$P_m = \frac{E_b V}{X_s} \sin \alpha$$



SUMMARY

Power input and power developed equations



KEEP
LEARNING..
Thank u

SEE YOU IN NEXT CLASS